

1160 0004

PROPERTY NAME: Guinseck Claims

OTHER NAMES: \_\_\_\_\_

MINERAL COMMODITY(IES): Mn

TYPE OF DEPOSIT: \_\_\_\_\_

ACCESSIBILITY: Location is probably at prospect symbol on map.

OWNERSHIP: \_\_\_\_\_

PRODUCTION: None.

HISTORY: \_\_\_\_\_

*Esmeralda County*

County: Esmeralda Item 16

Mining District: Gilbert? (Coaldale)

AMS Sheet: Tenopah GOLDPJE

Quad Sheet: Rhyolite Ridge 15

NE/4SW/4

Sec. 33, T 2N, R 37E

Coordinate (UTM):

North	4	2	0	4	2	5	0	m
East	0	4	2	3	8	0	0	m
Zone	+11							

DEVELOPMENT: Bulldozer road, recent drill hole, probably for uranium.

ACTIVITY AT TIME OF EXAMINATION: None.

GEOLOGY: The prospect consists of an outcrop of brown to black, iron-and manganese- oxide bearing siliceous sinter only 1m thick and 10m long. It is doubtful if it extends into the hillside more than a few meters. The siliceous material appears to be a spring sinter deposit; it is often finely laminated and it overlies a 15-20 cm zone of (cemented welded tuff fragments that appear to be a regolith on a solid outcrop of rhyolitic welded tuff. The tuff unit is probably the same one that is present about 0.5 km to the at the Coaldale uranium property. However, the sinter and surrounding rocks are not anomalously radioactive here. The sinter is downslope from a 6-8cm of clay-rich material that is hydrothermally? altered rhyolite welded tuff (smectite? clays). The sinter is cut by small, cross-cutting veinlets of manganese-oxide minerals.

The sinter may be associated with a fault zone here; there is a wide fault breccia zone to the west, and a slickensided surface (near horizontal slickensides) occurs just below the sinter. Also, a fault may form the mountain front here. However a drill hole the south of the sinter (and presumably across the proposed fault) hit welded tuff, but shows no indications (in the cuttings) of sinter. If there is a fault here it would be northeast -trending. The sinter is nearly horizontal, suggesting formation after most faulting.

The most likely suggestion is that this prospect is a sinter which may be related to a fault zone. The hot spring solutions could also have caused the clay alteration. The question is: is the sinter related to uranium-and molybdenum-bearing veins nearby in the range? The geochemistry may help answer this.

The hill behind the prospect is apparently entirely rhyolitic welded tuff also.

REMARKS: Sample 460 is of the sinter material.  
Photo G822-14 is of the prospect.

REFERENCES: \_\_\_\_\_

EXAMINER: L.J. Garside

DATE VISITED: 13 Jul 82