



1. ACCESS ROAD NEEDS WORK, EXTREMELY ROUGH IN PLACES WITH LAST STEEP TURN NOT POSSIBLE WITHOUT 4 WHEEL DRIVE. SOME PARKING SPACES COULD BE CREATED AT WORKINGS BUT AN AREA NEAR CAMP COULD BE CLEARED AND LEVELED FOR ADEQUATE PARKING. A STEEP PATH LEADS TO THE WORKINGS A SHORT DISTANCE UP HILL.
2. MANY BUILDINGS AT CAMP AND MILL ARE STILL STANDING WITH EQUIPMENT STILL IN TUNNELS.
3. TUNNELS AND WORKINGS GENERALLY STABLE. VANDALISM TO CIVIL DEFENSE SUPPLIES, SHAFT TIMBERS DOWN TO NO.4 LEVEL FROM NO.1 WORKINGS HAVE BEEN BURNED AND ADDERS DAMAGED. A SMALL AMOUNT OF WORK NEEDED TO RESTORE. NO.4 LEVEL IS ACCESSIBLE FROM MAIN ADIT.
4. VENTILATION IS GENERALLY GOOD EXCEPT FOR NO.1 WORKINGS SO. NO.2 AND NO.3 CLOSED OFF WITH BACK FILL. LADDERS FROM MAIN ADIT AND NO.2 TUNNEL DAMAGED. FLOOR OF WORKINGS ROUGH AND VENTILATION RESTRICTED. NO.3 WORKINGS NEED CONSIDERABLE REPAIR TO BE USED AS SHELTER AREA.
5. DANGER AREAS IN OTHER PARTS OF WORKINGS NEED LITTLE WORK TO MAKE THEM SAFER.



MAGNETIC NORTH 

SCALE: 1" = 25'



A horizontal line with vertical tick marks at each end. The left tick mark is labeled '0' and the right tick mark is labeled '25'.

FT.

NOTE: OUTSIDE TEMPERATURE = 86°
INSIDE TEMP. AT LEVEL 4835' = 66°

30

DATE 6-7-68	BY FM	FREDRIC H. MOLL ARCHITECT 3135 INDUSTRIAL ROAD PHONE 735-3040 LAS VEGAS, NEVADA 89102	NATIONAL FALLOUT SHELTER UPDATING SURVEY FOR NAVAL FACILITIES ENGINEERING COMMAND CLARK COUNTY CIVIL DEFENSE	ARGENTENA MINE		SHEET	
REVISIONS				E 1/2 SECT 33 T 24S R 58E FACILITY NO. 00192	GOODSPRINGS , NEVADA STD. LOC. NO. 7411-0017		
BY				SPACES 1672	SPACES WITH VENT 1846		OF 2

Item m. 13 (30)
032-003-0136