

0830 0014

UNITED STATES BUREAU OF MINES

(151)
Item 15PRELIMINARY EXAMINATION REPORTState Nevada County Lander Mineral Products TungstenName of property Goldacres Mine

Owner _____ Address _____

Lessee or
Operator Harry W. Treweek Address Beowawe, NevadaLocation Near south end of the Bullion Mining District in Townships 27 and 28 N., Ranges
46 and 47 E., 26 miles southwest.

Sample No.	% WO ₃	Description	Examined July 1943
308	0.01	Grab sample muck pile	
309	0.01	100' level - 65' from shaft	
310	0.04	100' level - 42' " "	
311	0.05	80' level - east face	

History and production During 1934 to 1941 the company developed and mines 50,000 tons of gold ore.

Type Deposit (Goeolgy) Country rocks are carboniferous sediments which are intruded by porphyry. In one area of tactite gold values, but no tungsten, occurred and has been the scene of notable activity. A considerable distance away to the southeast scheelite is noted in the tactite, some ~~distances~~ quartz calcite veins carrying small amounts of scheelite were also noted in this area.

Mine Workings Considerable workings in a developed mine which was shut down in 1942 because of WPB Order L-208.