


3. WELL MAINTAINED GRAVEL ROAD ON MINING PROPERTY INSIDE GATE.
4. ADEQUATE PARKING FOR NUMEROUS CARS ON FLAT JUST OUTSIDE MINE ENTRANCE. THE WIDE ROAD JUST BEYOND THIS AREA CAN ACCOMMODATE THE REST OF THE CARS.
5. NUMEROUS BAYS HAVE THE DANGER OF DRY FALL. HEAVY ROOF FALL AT THE WEST END OF THE MINE MAKES THIS AREA UNUSABLE. RECOMMEND THAT MINE BE INSPECTED BY A MINING ENGINEER.
6. LARGE VENT TO SURFACE - 30' ABOVE - 550' BACK FROM ENTRANCE GIVES THE MINE GOOD VENTILATION.
7. OUTSIDE TEMPERATURE = 95°  
TEMP 400' INSIDE = 65°



DATE 6-7-68	BY FM	FREDRIC H. MOLL ARCHITECT  3135 INDUSTRIAL ROAD PHONE: 735-3040  LAS VEGAS NEVADA 89102	NATIONAL FALLOUT SHELTER UPDATING SURVEY FOR NAVAL FACILITIES ENGINEERING COMMAND CLARK COUNTY CIVIL DEFENSE	WATER TANK NO 2 - BLUE DIAMOND MINE  FACILITY NO. 05248 BLUE DIAMOND, NEVADA STD. LOC. NO. 7411-0017	SHEET 1
REVISIONS	BY				

[illegible]