PROPERTY NAME: Treasure Hill Property OTHERNAMES: Several old mines in area MINERAL COMMODITY(ES): AE TYPEOF DEPOSIT: COUNTRIBITY: See topo map OWNERSHIP: (?) Silver King Mines (?) PRODUCTION: See old NBMC Publications HISTORY: """" DEVELOPMENT: ACTIVITY AT TIME OF EXAMINATION: Recent heap-leach operation by Iner Ericksons's group. Not curren in operation. GEOLOGY: REMARKS: (1) Two pictures taken-slide #30. Looking east at old workings - now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. Ceneral representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. Slide #33. Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - Further down road.	0 0041	
OTHERNAMES: Several old mines in area MINERAL COMMODITY(ES): AE TYPE OF DEPOSIT: CONNERSHIP: (?) Silver King Mines (?) OWNERSHIP: (?) Silver King Mines (?) FRODUCTION: See old NBMG Publications HISTORY: " " " " " " " " " " " " " " " " " " "	0 0041	(344) Item
OTHERNAMES: Several old mines in area MINERAL COMMODITY(ES): AE TYPE OF DEPOSIT: CONNERSHIP: (?) Silver King Mines (?) FRODUCTION: See old NBMG Publications HISTORY: " " " " " " " " " " " " " " " " " " "	PRODERTY NAME. Treasure Hill Property	County: White Pine
MNERAL COMMODITY(ES): A8 TYPE OF PROSIT: COURT SERVICES SERVITY: See topo map COWNERSHIP: (?) Silver King Mines (?) CONNERSHIP: (?) Silver King Mines (?) CONNERSHIP: (?) Silver King Mines (?) PRODUCTION: See old NBMG Publications HISTORY: """" """ COORDINATE (UTM): NOTH 4, 3,4,2,2,5,5,6 East 0,6,3,0,9,5,5 East 0,6,3,0,9,5 East 0,6,3,0,9 East 0,		Mining District: White Pine
TYPEOF DEPOSIT: ACCESSIBILITY: See topo map OWNERSHIP: (?) Silver King Mines (?) OWNERSHIP: (?) Silver King Mines (?) PRODUCTION: See old NBMG Publications HISTORY: " " " " " " " " " " " " " " " " " " "		AND Short Elv
ACCESSIBILITY: See topo map OWNERSHIP: (?) Silver King Mines (?) PRODUCTION: See old NBMG Publications HISTORY: " " " " " " " " " " " " " " " " " " "		
ACTIVITY ATTIME OF EXAMINATION: REMARKS: (1) Two pictures taken—slide #30. Looking east at old workings—now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area. (7) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures taken—slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads. Stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton — further down road.	TYPE OF DEPOSIT:	Quad Sneet:
PRODUCTION: See old NBMG Publications HISTORY: " " " " " " " " " " " " " " " " " " "	ACCESSIBILITY: See topo map	Sec. 30 , T 16N , R 5
REMARKS: (1) Two pictures taken—slide #30. Looking east at old workings—now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33. Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton — further down road.	OWNERSHIP: (?) Silver King Mines (?)	Coordinate (UTM):
REMARKS: (1) Two pictures taken- slide #30. Looking east at old workings - now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	HISTORY:	East 0 6 3 0 9 5 0
REMARKS: (1) Two pictures taken- slide #30. Looking east at old workings - now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	DEVELOPMENT:	
REMARKS: (1) Two pictures taken- slide #30. Looking east at old workings - now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	ACTIVITY AT TIME OF EXAMINATION: Recent heap-leach operation by Ir	ner Ericksons's group. Not curren
REMARKS: (1) Two pictures taken- slide #30. Looking east at old workings - now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	in operation.	
REMARKS: (1) Two pictures taken- slide #30. Looking east at old workings - now reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	GEOLOGY:	
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
reworked by dozer & track. Slide #31 same spot as #30 but looking north down throu the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
the heart of Treasure Hill workings. Area has been reworked with dozer loader & tr with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	DEMARKS. (1) Two pictures taken slide #20 Los	oking oast at old workings - now
with material having been hauled down to leach pads. (2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.		
(2) No attempt to distinguish individual workings. (3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as	#30 but looking north down throu
(3) Sample #932. General representative sample of area.(?) (4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been	s #30 but looking north down throu en reworked with dozer loader & tr
(4) Remains of 4-5 old stone buildings at south end of workings. (5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad	s $\#30$ but looking north down throu en reworked with dozer loader & tr ds.
(5) Two pictures slide #32. Looking south into old workings. Slide #33 Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual	s #30 but looking north down through en reworked with dozer loader & tr ds. L workings.
Looking east of #32 but still looking south from same spot as #32. Looking at work (6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative	s #30 but looking north down through reworked with dozer loader & trals. I workings. E sample of area.(?)
(6) Slide #34. Taken at north end of workings, looking south at remains stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings a	s #30 but looking north down through reworked with dozer loader & trals. L workings. E sample of area.(?) At south end of workings.
stone building & old workings. (7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings a (5) Two pictures slide #32. Looking sou	s #30 but looking north down through reworked with dozer loader & trds. I workings. E sample of area.(?) at south end of workings. ath into old workings. Slide #33
(7) Slide #35. Looking north from "new" haul road down into town site of Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings a (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from s	s #30 but looking north down through reworked with dozer loader & trads. L workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work
Hamilton, leach pads, stripping building, holding ponds, camp, etc. (8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings a (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from s (6) Slide #34. Taken at north end of wo stone building & old workings.	s #30 but looking north down through reworked with dozer loader & trads. L workings. E sample of area.(?) At south end of workings. Ath into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains
(8) Slide #36. Same as #35 only closer to Hamilton - further down road.	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings a (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from s (6) Slide #34. Taken at north end of wo stone building & old workings.	s #30 but looking north down through reworked with dozer loader & trads. L workings. E sample of area.(?) At south end of workings. Ath into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains
REMARKS:	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been with material having been hauled down to leach pade (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sour Looking east of #32 but still looking south from some (6) Slide #34. Taken at north end of workings to building & old workings. (7) Slide #35. Looking north from "new"	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. Ath into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of
REMARKS:	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some stone building & old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
REMARKS:	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some stone building & old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has bee with material having been hauled down to leach pad (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some stone building & old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been with material having been hauled down to leach pade (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some (6) Slide #34. Taken at north end of wo stone building & old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding (8) Slide #36. Same as #35 only closer	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been with material having been hauled down to leach pade (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some (6) Slide #34. Taken at north end of workings old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding (8) Slide #36. Same as #35 only closer	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been with material having been hauled down to leach pade (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some (6) Slide #34. Taken at north end of workings old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding (8) Slide #36. Same as #35 only closer	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been with material having been hauled down to leach pade (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some (6) Slide #34. Taken at north end of workings old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding (8) Slide #36. Same as #35 only closer	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been with material having been hauled down to leach pade (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some (6) Slide #34. Taken at north end of wo stone building & old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding (8) Slide #36. Same as #35 only closer	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.
	reworked by dozer & track. Slide #31 same spot as the heart of Treasure Hill workings. Area has been with material having been hauled down to leach pade (2) No attempt to distinguish individual (3) Sample #932. General representative (4) Remains of 4-5 old stone buildings at (5) Two pictures slide #32. Looking sout Looking east of #32 but still looking south from some (6) Slide #34. Taken at north end of wo stone building & old workings. (7) Slide #35. Looking north from "new" Hamilton, leach pads, stripping building, holding (8) Slide #36. Same as #35 only closer	s #30 but looking north down through reworked with dozer loader & trads. I workings. E sample of area.(?) At south end of workings. At into old workings. Slide #33 Same spot as #32. Looking at work orkings, looking south at remains haul road down into town site of ponds, camp, etc.

EXAMINER: RBJ DATE VISITED: 7-17-81

REFERENCES: .