(129)

Itom 7

waters which later deposited tufa derived from calcerous beds in sediments. Deposit thought to be hypogene. Hydrothermal minerals with abundant Barite. Tufa is not mineralized by Mn and iron but angular shale fragments are cemented by the mineralized material.

FLOW SHEET - GOLCONDA TUNGSTEN MILL

Coarse ore bin (too small)

Jaw crusher

Rolls

Elevator

Screen

Rotary kiln dryer

Bin

Ball mill Cyclone dust ppt. (dry) and screen

Na₂CO₃ NaCL Coal

100 tons ½ to 1% WO3 solution precipitate per day.

Moisture & mixer-rotary

Dwight-Lloyd sintering machine

Ball mill (wet)

3 agitators in series

No.1 No.2 No.3 No. 4

Storage tank Tails 0.27% WO3

and heat exch.

Tails 0.01% WO3

First pot. (impurities)

CaWO3 Pot.

drum Filter

65 deg. C Water heaters

Rotary drier

65% WOz concts.

June 25 ADELAIDE-CROWN SYNDICATE Roy Hardy, U.N. Manager

Property about 10 miles south of Golconda. Dodge Bros. contracting stripping and hauling ore. Two men breaking ore for shovel. 22¢ a yard for stripping, 27¢ per ton ore to mill. \$1.25 per ton milling cost, \$2.00 per ton total cost - \$4.00 ore. N-S striking ore body. Stripping 2:1.

Custom ore Bin Mine Bin Grizzly

Preg. solution \$2.20 per ton
Nal thickener Butters lead purifier

3-ft. E-Y gyratory Simons vib. 5/8" 3 agit. series Dereator tank screen

Zinc dust

Fine ore bin Mill sol'n.

V type

vezin

4-tray wash. thick.

Dorr. class. 8' Hardinge 200 HP ind.

Bullion furnace

Tails Barren sol'n.