U.S. DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY

EXPLANATION Granite Porphyry Pb, Zn, Cu, Mineralization Contact Fault, showing dip (Dashed where approx. located) Vertical fault Strike and dip of beds Head of shaft \boxtimes Foot of raise Head of raise MM Lagging in drift

MAP OF 500 LEVEL STANDING ELK MINE BULLION MINING DISTRICT, ELKO COUNTY, NEVADA

Mapped by G. C. Simmons and D. C. Arnold

FIG.

Them ma

000