

SERIAL NUMBER Nevada 034444
 PATENT #1166594 DATE Dec. 5, 1956

T. 25 N., R. 35 E., M. D. M.

S.E. $\frac{1}{4}$ Sec. 26

S.W. $\frac{1}{4}$ Sec. 26

JOHNS

MANVILLE

Disc. Mon. 1.

Trenches

Cuts

Trenches

Gulch

Road

Approx. Position

MINERAL SURVEY No. 4824 NEVADA

CLAIM OF
 UNITED STATES GYPSUM COMPANY

KNOWN AS THE
 JOHNS MANVILLE LODGE

SITUATE IN
 SEC. 26, T. 25 N., R. 35 E., M. D. M.
 PERSHING COUNTY
 UNORGANIZED MINING DISTRICT
 NEVADA LAND DISTRICT

LAT. 40°00' N., LONG. 118°00' W.
 AT COR. NO. 3, JOHNS MANVILLE LODGE

0 50 100 200 300 400 500 600
 FEET

MAGNETIC DECLINATION, 18°30' EAST.

SURVEYED, DEC. 12 TO DEC. 16, 1951,
 BY FREDERIC THOMASSON, MINERAL SURVEYOR.

UNITED STATES DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT
 DIVISION OF CADASTRAL ENGINEERING
 SAN FRANCISCO, CALIFORNIA
 JANUARY 11, 1954

I HEREBY CERTIFY THAT THIS PLAT
 OF MINERAL SURVEY NO. 4824, NEVADA, IS
 STRICTLY CONFORMABLE TO THE FIELD NOTES
 OF SAID SURVEY WHICH HAVE BEEN EXAMINED
 AND APPROVED.

Frank W. Chapin
 ACTING OFFICE CADASTRAL ENGINEER.

4730 0069

Table Mountain Dist. Pershing County