

0030 0004

UNITED STATES BUREAU OF MINES

Clark County
Cl-3
Item 11

PRELIMINARY EXAMINATION REPORT

State Nevada County Clark Mineral Products Mica

Name of property Oversight Mica

Owner H. B. Carpenter 5540 Hollywood Blvd., Hollywood, Calif.
Wm. C. Thompson Address 309 1/2 North Kenmore Ave., Los Angeles, Calif.

Lessee or
Operator _____ Address _____

Location _____

Examined February 1944.

History and production Since 1942 about 50 tons of scrap mica with some punch and book sizes. Mine was inactive at the time of the examination.

Type Deposit (Geology) Gneiss schists and quartzite are cut by igneous dikes and plug. The Oversight Mica Mine occurs in one of these plugs or dikes which is pegmatitic. This intrusion is composed of ribs of feldspar and quartz interlaced with small veins of muscovite mica. The mica bearing zone appears to be about 200 feet long and 100 feet wide at its widest place.

Mine Workings A few open pits and trenches.