

EXPLANATION





Fault, showing dip
Dashed where approximately
located


Vertical fault


Top of cut


Foot of cut











SKETCH MAP OF TRENCHES #1-5 (STAGE II) RED ROCK MINE, ESMERALDA COUNTY, NEVADA

9 40

Iten M2

89

1860 0057.